

Wire Gage Conversion (Table 2)

| AWG Size | MM* | Stranding | | Diameter | |
|----------|-------|--------------------------|------------------------|-----------------|----------------|
| | | N x OD inches | N x OD MM | Inches | MM |
| 8AWG | 8.30 | 1 x 0.128 | 1 x 3.251 | 0.128 | 3.251 |
| 10AWG | 5.3 | 1 x 0.102 7 x 0.0385 | 1 x 2.59 7 x 0.978 | 0.102 0.116 | 2.59 2.95 |
| | 4.0 | 1 x 0.089 7 x 0.0335 | 1 x 2.26 7 x 0.85 | 0.089 0.100 | 2.26 2.55 |
| 12AWG | 3.32 | 1 x 0.081 7 x 0.032 | 1 x 2.05 7 x 0.813 | 0.081 0.096 | 2.05 2.44 |
| | 2.5 | 1 x 0.070 7 x 0.0266 | 1 x 1.78 7 x 0.67 | 0.070 0.080 | 1.78 2.01 |
| 14AWG | 2.07 | 1 x 0.064 7 x 0.0253 | 1 x 1.63 7 x 0.635 | 0.064 0.076 | 1.63 1.93 |
| | 1.5 | 1 x 0.054 7 x 0.0206 | 1 x 1.38 7 x 0.52 | 0.054 0.063 | 1.38 1.57 |
| 16AWG | 1.32 | 1 x 0.051 7 x 0.0201 | 1 x 1.29 7 x 0.511 | 0.051 0.060 | 1.29 1.53 |
| | 1.0 | 1 x 0.045 7 x 0.0169 | 1 x 1.13 7 x 0.43 | 0.045 0.051 | 1.13 1.30 |
| 18AWG | 0.812 | 1 x 0.0407 7 x 0.0159 | 1 x 1.02 7 x 0.406 | 0.040 0.048 | 1.02 1.22 |
| | 0.75 | 1 x 0.039 7 x 0.0146 | 1 x 1.00 7 x 0.37 | 0.039 0.044 | 1.00 1.11 |
| 20AWG | 0.52 | 1 x 0.032 7 x 0.0126 | 1 x 0.813 7 x 0.32 | 0.032 0.038 | 0.813 0.970 |
| | 0.50 | 1 x 0.0315 7 x 0.0118 | 1 x 0.80 7 x 0.30 | 0.0315 0.035 | 0.80 0.90 |
| 22AWG | 0.325 | 1 x 0.025 7 x 0.010 | 1 x 0.635 7 x 0.254 | 0.025 0.030 | 0.635 0.790 |
| 24AWG | 0.205 | 1 x 0.020 7 x 0.008 | 1 x 0.511 7 x 0.203 | 0.020 0.024 | 0.511 0.610 |
| 26AWG | 0.128 | 1 x 0.0159 7 x 0.0063 | 1 x 0.406 7 x 0.16 | 0.0159 | 0.406 |
| 28AWG | 0.080 | 1 x 0.0126 7 x 0.0050 | 1 x 0.320 7 x 0.127 | 0.0126 | 0.320 |
| 30AWG | 0.051 | 1 x 0.010 7 x 0.0040 | 1 x 0.254 7 x 0.102 | 0.010 | 0.254 |
| 32AWG | 0.032 | 1 x 0.0080 | 1 x 0.203 | 0.0080 | 0.203 |
| 34AWG | 0.020 | 1 x 0.0063 | 1 x 0.160 | 0.0063 | 0.160 |
| 36AWG | 0.013 | 1 x 0.0050 | 1 x 0.127 | 0.0050 | 0.127 |